

tree to ascertain if possible the place of the original Witness tree to the Township corner Then to Quarter stake Same course Then went to N.E. corner of Section 6 or rather to S.E. corner of 31 But could not find the corner of Section 6 Agreeably to the field notes Started from corner of 31 Then S. 84° W. 39.91½ Chains to the Quarter stake of Section 31. Then Went to the N.E. corner of Section 36. T. 8. N. R. 7. W. S. 6° E. 3½ Miles and 75 Links of the chain to the Quarter Stake of Section 24. T. 7. N. R. 7. W. on the Range line and missed the Quarter Stake on the left hand 69½ Links Then went back to the Township corner and laid 47 Links of the Chain Westward from the end of the first mile which I run from N.E. corner of Section 36. T. 8. N. R. 7. W. and made the Township corner at a stake or W. Oak post Deposited to feet in the Earth and presents some more than one foot above the Surface. Then went to the Quarter stake on the South Side of Section 6 and Deposited a stone Where the original Quarter stake stood with the following Letter and figures engraven thereon, to wit, (1/4 S) Then South 83½° W. 43.78 Chains to the Range line 80 chains South of the Township corner and planted a stone with the following letters and figures engraven thereon, (T. 7. N. R. 6. W. S. 6. S. 7) for Robert and Osborn Harrow. Then went to Quarter Stake of Section 31 on the North Side of Section 6. Then S. 6½° E. 77.60 Chains to the stone which I had planted on south side of Section and missed said stone 12 Links westward Then went westward on the Section line 21.89 Chains and made a corner at a stone at a W. Oak.

- Ins. dia. N. Links and

Then N. 6. 28° W. 39.90 chains to a stone corner Then S. 83¾° W. 21.43½ chains to the Range line and made a corner at a stone at a Jack Oak.

16 Ins. dia. N. 23° E. 2.33¾ Links Then went to N.E. corner of W. 1/2 of N. W. 1/4 of Section 6. T. 7. N. R. 6. W. and made a corner for Baldwin Harrow on the Township line 21.23 chains from the Township corner Eastward at a stone at a Hickory

Ins. dia N. E. Links  
Robert Harrow and Aquilla Moss. Chain Bearers.  
John B. Kelshaw C.S. G. C.

No 27

Surveyed for Osborn Harrow in Section 7. T. 7. N. R. 6. W. N. W. 1/4 Whereas 2 corners has already been put to record in No. 26. Then planted a stone corner on the Range line in Prairie one mile and a half south of the Township corner with the following letter and figures thereon (1/4 S.) Then N. 84° E. 86.23 chains and missed the place where we supposed the original Quarter stake stood on the East side of Section. 88 Links Northward the

+ The reason I say above, supposed, we could not find any trees to exactly to agree with the field notes. Then went Back on line run 40.03 chains and laid southward 47.70 Links and made a corner at a stone at a

Links and Ins. dia - Links  
Then. N. 7° W. 110.89 Chains and missed Stone Quarter Stake on North Side of Section 1.60 Links Eastward calculated variation and found true course N. 9° 14' W. by calculation. as there are <sup>but</sup> few if any original known corners to This Section Seven That can be found I expect that the two last made corners will have to be relocated when the section comes completely Surveyed

Robert Harrow and Aquilla Moss.  
Chain Bearers. John B. Kelshaw. C.S. G. C.